

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 128177

RECEIVED FROM Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080114-7

DATE RECD 1-22-47
P. O. NO. 69204
VENDOR PACKING SLIP NO. 11736
ACCT. OR R. W. O. NO.
S. O. NO.

CHARGE TO

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	REMARKS
QUANTITY RECEIVED									
DRAWING NO. AND DESCRIPTION.									
10		000000	10161		00	10	02		

RECEIVED BY

INSPECTED BY

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 128186

RECEIVED FROM

DATE RECD 1-22-47
P. O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	REMARKS
QUANTITY RECEIVED									
25		000000	10161						
DRAWING NO. AND DESCRIPTION.									
25			COUPLING ASSY						
REULATOR 85814									

RECEIVED BY

INSPECTED BY

REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080114-7